# The Deleterious Chemical Effects of Concentrated Deicing Solutions on Portland Cement Concrete

Principal Investigator

Larry Sutter Michigan Tech

Co-Principal Investigators

Karl Peterson, Tom Van Dam Michigan Tech

Doug Hooton
Gustavo Julio-Betancourt
University of Toronto

# Background

#### Problem Statement

- Keeping roads safe & passable in winter weather is a primary concern of SHAs
- Always looking for easier, safe, cost effective means for highway deicing/anti-icing
  - Both accomplished by the use of various brines
  - Chemicals are effective for deicing/anti-icing
- Chemicals have not been proven to be safe for concrete – may cause premature deterioration

Deicer Scaling - Deicer chemicals may contribute by chemically interacting with cement paste



# Paste Dissolution/Softening

Chemical attack of concrete - Usually slow process



# Corrosion of Reinforcing Steel

Already well documented and understood - Not a focus of this research



# Background

# Research Objectives

- Determine the <u>long term effects on concrete</u>
   from exposure to concentrated solutions of MgCl<sub>2</sub>, NaCl, CaCl<sub>2</sub>, and CMA
- Identify protective or design strategies that minimize material damage from chemical exposure

# Approach

- Characterization of Field Specimens
  - Determine distress mechanisms present in the field
- Phase I Laboratory Experiments
  - Performed on mortar specimens (cement, sand, and water)
  - Identify distress mechanisms
  - Assess the role of mixture properties and deicer types
- Phase II Laboratory Experiments
  - Performed on <u>concrete</u> (cement, sand, aggregate, and water)
  - Confirm distress mechanisms active in concrete
  - Determine the role of deicer concentration, concrete mixture design, and the effectiveness of sealants

# Characterization of Field Specimens

# Five Sites Identified by Panel

- Colorado, State Highway 83, South of Denver near Milepost 57
- Iowa, eastbound US Highway 34, western end of the Burlington Bridge.
- Idaho, westbound Interstate Highway 184 west of Boise, near milepost 3
- Montana, westbound Interstate Highway 90 bridge deck near milepost 117
- South Dakota, eastbound 26th Street left turn lane

#### Two Additional Sites Identified

- Montana, eastbound Interstate Highway 90 bridge deck, near milepost 61.8, Tarkio interchange
- Montana, westbound Interstate Highway 90 bridge deck, near milepost 37.2, Sloway interchange

#### Phase I - Details


- Expose mortars to deicer solutions at fixed concentrations (less than typical application conc.)
- Monitor Physical Effects
  - Strength Loss
  - Expansion
  - Freeze-Thaw Performance
- Monitor Chemical Effects
  - Petrographic analysis to identify alterations to the mortar

#### Phase I - Details

- Five different deicer solutions
  - MgCl<sub>2</sub> Magnesium Chloride (15 wt%)
  - CaCl<sub>2</sub> Calcium Chloride (17 wt%)
  - NaCl Sodium Chloride (23 wt%)
  - Proprietary Magnesium Based Agricultural Products
  - CMA Calcium Magnesium Acetate
  - Saturated limewater (control)
- Exposed for various times
- Exposed at different temperatures (40, 72, 135°F)

#### Phase II - Details

- Concrete mixtures were made using
  - high quality, partially crushed gravel coarse aggregate
  - natural sand
  - 564 lb/yd<sup>3</sup> Type I/II cement
  - vinsol resin and synthetic AEA
  - w/c of 0.45 and 0.55
- Two additional mixtures were prepared,
  - 15 percent replacement of cement with Class F fly ash
  - 35 percent replacement of cement with ground blast furnace slag (GBFS)
- Exposed to same deicers as Phase I



# South Dakota EB 26th Street Left-turn lane onto NB Interstate Highway 29









| Sample ID  | SD_01    | SD_04           |
|--|----------|-----------------|
| Location   | at joint | away from joint |
| Raw data   |          |                 |
| Total traverse length (mm)                             | 3625.456 | 3625.456        |
| Area analyzed (cm <sup>2</sup> )                       | 71.0     | 71.0            |
| Air stops  | 85       | 91              |
| Paste stops  | 396      | 382             |
| Aggregate stops  | 907      | 915             |
| Secondary deposit stops                                | 0        | 0               |
| Total stops  | 1388     | 1388            |
| Number of air intercepts                               | 1577     | 1420            |
| Number of filled void intercepts                       | 2        | 0               |
| Results  |          |                 |
| Air vol.%  | 6.1      | 6.6             |
| Paste vol.%  | 28.5     | 27.5            |
| Aggregate vol.%  | 65.3     | 65.9            |
| Secondary deposit vol.%                                | 0.0      | 0.0             |
| Existing average chord length (mm)                     | 0.141    | 0.167           |
| Existing paste/air ratio                               | 4.7      | 4.2             |
| Existing air void specific surface (mm <sup>-1</sup> ) | 28.4     | 23.9            |
| Existing air void frequency (voids/m)                  | 435      | 392             |
| Existing spacing factor (mm)                           | 0.158    | 0.176           |
| Original average chord length (mm)                     | 0.141    | 0.167           |
| Original paste/air ratio                               | 4.7      | 4.2             |
| Original air void specific surface (mm <sup>-1</sup> ) | 28.4     | 23.9            |
| Original air void frequency (voids/m)                  | 436      | 392             |
| Original spacing factor (mm)                           | 0.158    | 0.176           |

--

# South Dakota EB 26th Street Left-turn lane onto NB Interstate Highway 29


• Stereomicroscope image of polished surface from core SD\_04, magnified here approximately 4x

• Stereomicroscope image of polished surface from core SD\_04, magnified here approximately 22x.






# South Dakota EB 26th Street Left-turn lane onto NB Interstate Highway 29





• Histogram comparing cement paste pixel intensities using all 12 frames as collected from thin sections prepared from cores taken at the joint versus cores taken mid-panel.



# Montana, eastbound Interstate Highway 90 bridge deck, near milepost 61.8, Tarkio interchange








|             | Sample ID  | T-2             |  |
|-------------|--|-----------------|--|
|             | Location   | Area in<br>Good |  |
|             | Location   | Condition       |  |
|             | Raw data   |                 |  |
|             | Total traverse length (mm)                             | 3772.1          |  |
|             | Area analyzed (cm <sup>2</sup> )                       | 73.9            |  |
|             | Air stops  | 70              |  |
|             | Paste stops  | 413             |  |
|             | Aggregate stops  | 961             |  |
|             | Secondary deposit stops                                | 0               |  |
|             | Total stops  | 1444            |  |
|             | Number of air intercepts                               | 617             |  |
|             | Number of filled void intercepts                       | 0               |  |
| Results     |  |                 |  |
|             | Air vol%   | 4.9             |  |
|             | Paste vol%   | 28.6            |  |
|             | Aggregate vol%   | 66.6            |  |
|             | Secondary deposit vol%                                 | 0.0             |  |
|             | Existing average chord length (mm)                     | 0.370           |  |
|             | Existing paste/air ratio                               | 5.9             |  |
|             | Existing air void specific surface (mm <sup>-1</sup> ) | 13.5            |  |
|             | Existing air void frequency (voids/m)                  | 164             |  |
| <b>&gt;</b> | Existing spacing factor (mm)                           | 0.296           |  |
|             | Original average chord length (mm)                     | 0.370           |  |
|             | Original paste/air ratio                               | 5.9             |  |
|             | Original air void specific surface (mm <sup>-1</sup> ) | 13.5            |  |
|             | Original air void frequency (voids/m)                  | 164             |  |
| >           | Original spacing factor (mm)                           | 0.296           |  |

Montana, eastbound Interstate Highway 90 bridge deck, near milepost 61.8, Tarkio interchange


• Stereo microscope images to show air void structure on polished slab from core T-2.












Montana, eastbound Interstate Highway 90 bridge deck, near milepost 61.8, Tarkio interchange



X-ray map of Mg

# Summary - Characterization of Field Specimens

- No site examined showed clear, conclusive evidence of distress that could be linked directly to deicing chemicals
- Common observations included:
  - A reduction in paste density near joints and cracks
  - Higher chloride ingress in those areas with reduced paste density
  - Marginal or inadequate air-void systems
- The Tarkio Bridge (MT) had the strongest resemblance to concrete exposed to deicing solutions in the laboratory:
  - Magnesium enrichment at surface
  - Calcite deposits near crack at depth
- Pronounced efflorescence underneath the Tarkio bridge
- South Dakota showed significant chloride ingress relative to the age of the pavement



Cylinders exposed to MgCl<sub>2</sub> solution after 84 days of exposure @ 40 °F. From left to right: 0.40, 0.50, and 0.60 w/c mortar cylinders.



Cylinders exposed to CaCl<sub>2</sub> solution after 84 days of exposure @ 40 °F. From left to right: 0.40, 0.50, and 0.60 w/c mortar cylinders.



Cylinders exposed to NaCl solution after 84 days of exposure @ 40 °F. From left to right: 0.40, 0.50, and 0.60 w/c mortar cylinders.



Control cylinders exposed to lime water solution after 84 days of exposure @ 40 °F. From left to right: 0.40, 0.50, and 0.60 w/c mortar cylinders.




### Mechanism

- Specimens were held at a constant 40 °F so no freezing occurred that could result in the damage observed
- Expansion was caused by the formation of calcium oxychloride
- Results from the reaction of calcium hydroxide (*present in the hardened cement paste*) with chloride ions (*provided by the deicer*)


From left to right:
plane polarized light,
cross polarized light, and
epifluorescent mode images of thin
section prepared from cylinder
immersed in MgCl<sub>2</sub> solution.

- Petrographic Analysis
- Thin sections from 0.50 w/c specimens
- MgCl<sub>2</sub> and CaCl<sub>2</sub> show similar alteration
  - Ca(OH)<sub>2</sub> depleted region
  - Cracks in-filled with calcium oxychloride




From left to right:
plane polarized light,
cross polarized light, and
epifluorescent mode images of thin
section prepared from cylinder
immersed in CaCl<sub>2</sub> solution.

- Petrographic Analysis
- Thin sections from 0.50 w/c specimens
- MgCl<sub>2</sub> and CaCl<sub>2</sub> show similar alteration
  - Ca(OH)<sub>2</sub> depleted region
  - Cracks in-filled with calcium oxychloride



From left to right:
plane polarized light,
cross polarized light, and
epifluorescent mode images of thin
section prepared from cylinder
immersed in NaCl.

- Petrographic Analysis
- Thin sections from 0.50 w/c specimens
- NaCl and lime water controls show no alteration




From left to right:
plane polarized light,
cross polarized light, and
epifluorescent mode images of thin
section prepared from cylinder
immersed in lime water.

- Petrographic Analysis
- Thin sections from 0.50 w/c specimens
- NaCl and lime water controls show no alteration




Scanning electron microscope images of thin sections prepared from cylinders immersed in, from left to right, MgCl<sub>2</sub>, CaCl<sub>2</sub>, NaCl, and saturated lime solutions.

- SEM Analysis
- Backscattered electron images
  - Parallel cracks
  - Ca(OH)<sub>2</sub> and oxychloride deposition in the voids of the MgCl<sub>2</sub> and CaCl<sub>2</sub> specimens



From top to bottom: plane polarized light, cross polarized light, and epifluorescent mode.

- Petrographic Analysis
  - Cracks and air voids filled with remnant calcium oxychloride crystals in thin section prepared from MgCl<sub>2</sub> solution immersed sample




From top to bottom: plane polarized light, cross polarized light, and epifluorescent mode.


- Petrographic Analysis
  - Cracks and air voids filled with remnant calcium oxychloride crystals in thin section prepared from CaCl<sub>2</sub> solution immersed sample




### Compressive strength evolution with time of mortar cubes




### Length change of mortar bars




### Mass change of mortar bars









## X-ray diffractogram for mortars exposed to 22% CaCl<sub>2</sub> – 30d @5C












Laboratory Results - Phase II


# 17% CaCl<sub>2</sub> – 500 days – 40 deg F





# 15% MgCl<sub>2</sub> - 500 days - 40 deg F


# 15% MgCl<sub>2</sub> MBAP - 500 days - 40 deg F

















# Silane Sealer Profiles




Typical Diffusion Profiles for 0.45 *w/c* Concrete Exposed to 15% MgCl<sub>2</sub> - PCC, 15% Fly Ash, 35% GGBFS Mixtures



# Sorptivity of 15% MgCl<sub>2</sub> into 0.45 w/c Concrete Mixtures



# Freeze Thaw Testing - Length change of concrete prisms



Concrete prisms subjected to 133 cycles of freeze/thaw cycles in 17% CaCl<sub>2</sub>




Concrete prisms subjected to 133 cycles of freeze/thaw cycles in 15% MgCl<sub>2</sub>



### Concrete slabs at cycle 0

Pre-exposed to high concentration 1 year - scaling test at low concentration





23% NaCl + 3% NaCl

22% CaCl<sub>2</sub> + 4% CaCl<sub>2</sub>

### Concrete slabs at cycle 50






23% NaCI + 3% NaCI

22% CaCl<sub>2</sub> + 4% CaCl<sub>2</sub>

### Concrete slabs at cycle 100






23% NaCI + 3% NaCI

22% CaCl<sub>2</sub> + 4% CaCl<sub>2</sub>

X-ray diffractogram for surface of concrete slab exposed to 22%  $\operatorname{CaCl}_2$  for 1 year



- MgCl<sub>2</sub>, CaCl<sub>2</sub>, and proprietary deicers containing MgCl<sub>2</sub> cause expansion, cracking, and loss of strength for concrete and mortars exposed at 40 °F
- NaCl caused no observed distress to concrete, however it is known to be detrimental to reinforcing steel in concrete
- Results for CMA were mixed, in some tests causing degradation but not in others

- Of the deicers tested, MgCl<sub>2</sub> caused the highest amount of expansion and strength loss
- CaCl<sub>2</sub> caused the most visible damage in the shortest time
- In the tests performed, NaCl caused no observed strength loss or expansion
- Pessimum concentration determined for MgCl<sub>2</sub> was 20% and for CaCl<sub>2</sub> it was 22%

- MgCl<sub>2</sub> and CaCl<sub>2</sub> exposed specimens exhibited unacceptable expansion and change in dynamic modulus in freeze-thaw testing
  - Cyclic freeze-thaw exposure exacerbates the damage caused by these deicers
- In all cases, the mechanism of failure is the formation of oxychloride phases by the interaction of the deicer with calcium hydroxide in the hardened cement paste

- Concrete mixtures prepared with ground blast furnace slag or fly ash as a portland cement replacement <u>performed significantly better</u> in tests as compared to concrete prepared with portland cement only
- <u>Silane and siloxane sealants</u> both <u>improved</u> the <u>performance</u> of concrete exposed to deicing chemicals
- Sealants are a good maintenance strategy but need to be reapplied every 3-5 years in order to remain effective

# Questions

- How quickly will distress occur in "real-world" applications?
  - Exact concentration of deicers, as applied, varies
    - Concentration varies
    - Application rates
  - Deicers are <u>diluted by weather events</u> (positive)
  - When deicers are applied in an anti-icing strategy, high concentration solutions are presented to the concrete and if the weather doesn't occur <u>no dilution</u> results (negative)

## Questions

- What is the relationship between field observations and laboratory observations?
  - Field distress, in some cases resembles laboratory distress (positive)
  - Oxychloride phases were not seen in field samples. Why?
    - Oxychloride phases are very unstable and can alter between various states of hydration
    - Oxychloride phases can revert to other phases (e.g. calcite) which <u>ARE</u> seen in field cores

Montana, eastbound Interstate Highway 90 bridge deck, near milepost 61.8, Tarkio interchange

Laboratory tests confirmed that oxychloride phases quickly convert to calcite ( $CaCO_3$ - or calcium carbonate) when exposed to atmosphere in the presence of water

Calcite Deposits





# Future Work

• Determine life-cycle impact of deicers



# **Tuture Work**

• Determine life-cycle impact of deicers



# Future Work

• Determine life-cycle impact of deicers



### Future Work

- Other suggested areas for additional research include:
  - Further testing to determine the effect of different replacement levels of SCMs on the resistance of concrete to deicers
  - A detailed experiment to determine the effects of w/c on deicer related distress
  - A study of highway deicer chemical contributions to alkali-silica reaction (ASR)
  - Further testing to better understand field reports of scaling related to use of MgCl<sub>2</sub> and CaCl<sub>2</sub>