

GOODPASTURE COVERED BRIDGE REHABILITATION

165-foot-long heavy
timber Howe truss
main span

Bridge Location:
Vida, Oregon

Bridge Owner:
Lane County



International Conference on Timber Bridges, 2013

Greg Ausland, PE, Project Manager, gausland@obec.com

Tony LaMorticella, PE, SE, Sr. Project Engineer, TLaMorticella@obec.com

OBEC Consulting Engineers



BUILT IN 1938 BY LANE COUNTY



Under the supervision of veteran bridge builder Arthur C. Striker

TO CARRY GOODPASTURE ROAD ACROSS THE MCKENZIE RIVER FOR \$13,155

No. 16-2E-29

Goodpasture Bridge over McKenzie River in Co. Road No. Sec. 27 Tp. 14 S. R. 2 E. W. M.

PIERS AND ABUTMENTS						Issued	EST Total Final Cost
No. of Piers or Abutments	Number	Type	Material	Year Built	Name of Builder		
	2	Dumbell	Kemp Conc.	1937	Lane Co.		
	1	Abutment					
	4	Abutments					

BRIDGE						Issued	EST Total Final Cost
No. of Spans (and Bays)	No. of Spans	Length of Spans	Material	Type of Span	Year Built		
	1	165'	Wood	Howe Truss	1938-39	Lane Co.	
	2	19'	Wood	Frame Br.		"	
	3	23'	Wood	Frame Br.		"	

SKETCH OF BRIDGE

Reports, Receipts, Etc., on		Issued	Total Cost of Re- pairs and Expenses up to Year
1937-38			
Lumber	200,803'	3,679.43	
Labor		3,497.45	
Falsework, Poles and Piling		35.10	
Cement	1131 sacks	745.44	
Sand and Gravel	209 1/2 cu. yds.	208.48	
Hardware, Rods, bolts, spikes, iron, etc.		2,013.21	
Labor - Hauling		121.73	
Truck Rental		145.50	
Shingles - 61 @ \$3.00		183.00	
Labor shingling @ 1.20		61.00	
Engineering		109.36	
Miscellaneous		124.07	
Paint, Labor		194.65	
Paint, incomplete		37.77	
			\$13,154.41

19



Under construction 1938

Original construction invoice


THE MIGHTY MCKENZIE RIVER



from Google Earth

Fast pristine water, good fishing, home to many listed species of aquatic life

BRIDGE IS LIFELINE TO COMMUNITY SOUTH OF RIVER



Aerial view – Google Earth

BLIND CURVE AND NO SHOULDER OR TURN LANE FOR WESTBOUND TRAFFIC



Looking east up highway

BRIDGE CIRCA 1950



With H10 truck of the day

Typical
modern Oregon
log trucks

Substantially
heavier than
design load



One-log loads,
once common, now rare

Hazard to covered bridges even when empty


1972 STRUCTURAL DISTRESS

3

Left Truss

- ✓ L4-U5 - Good
- ✓ L5-U4 - Good
- U4-U5 Vert checking ext member
Butt joint int - Good
- ✓ Joint U5 Ext & int blocks are checking
- ✓ Joint L5 checking all blocks
- ✓ L5-L6 Vert & Horiz checks middle m.
- ✓ L5-U6 - ok
- L6-U5 vert check Bottom
- ✓ U5-U6 vert check ext m.
- ✓ Joint U6 checking m blocks
- ✓ Joint L6 Good
- L6-L7 - Int splice splitting


Rib's
SP-L's are
around all the
m's joints




- ✓ L7-U6 Good
- ✓ L6-U7 Horiz check
- ✓ U6-U7 Butt splice ext.
- ✓ Joint U7 - check int block
- ✓ Joint L7 - Good
- 1/4" space
ext. splice
- L7-L8 - splice middle member
Some spacer spreading - no load reduction

Inspector's notes documenting broken bottom chord splices

1986 CHORD SPLICE REINFORCEMENT DESIGN



Welded steel plate anchors to bottom chord segments with lag screws and 2½" diameter tie rods passing through timber truss diagonal members.



REPAIR ADDED >7 TONS OF DEAD LOAD BUT WAS ONLY MARGINALLY EFFECTIVE



Broken splices leaving gaps to 1/2"



Some rods were never engaged

Gaps not
closed by
tie rods



OVERLOADS

ATTN Doug 541-682-8994

OWNER: Gresham Tractor
 Truck 1-888-444-7904
 Log Loader

	Trac.	MANUFACTURER	LICENSE	SERIAL NO.
	Jeep			
	Trer.			
	Dist. Unit			

Wheels/Axle Spacing	12.5	5.9	4.5	13.2	4.5	32.6	4.5	14.1	4.5
Overall Length									
Wheel Width	8	8	8			10	9		
Gross Weight	12,000	44,000	41,000			40,000	40,000		
Wheelbase									
Wheel Size									
Wheel Rating									
Wheel Load									
Plate Load									

6/1/98
 Told Doug OK w/
 - Drive down center
 - 5 mph
 - 43k max Tandem

NOTES:

Post-It Fax Note	7671	Date	5-28	Pages	1
To	Bill Hall	From	Doug McCurt		
Company	ADFC	Company	Lease Co.		
Phone #		Phone #	682-6928		
Fax #		Fax #	682-8994		

MAY-28-98 03:27P
 18 P 7671
 541 682-8994
 P. 01

Approved overload request from 1998 GVW is 177,000 lbs.

LIGHTER ROOF IN 2010



Very heavy cement/wood fiber composite roofing was leaking



Replaced with much lighter and historically more appropriate cedar shingles

4-INCH SAG AT MID-SPAN EVEN WITH LIGHTER ROOF



2012 photo

TYPICAL RIVER LEVEL



Bridge soffit approximately 30 feet above hard rock stream bed, fast and deep water.
In-water work period is only 6 weeks, July 15 to September 1.

HIGH WATER




Water level can rise several feet in a few days

CORRECTING THE GEOMETRY FROM ABOVE

STEP 1



Temporary rail installed
and deck cut



Installing the first temporary steel
truss during night-time closure


FIRST TEMPORARY STEEL TRUSS IN PLACE



Standing vertical



Bearing on concrete pier




Temporary rail in place,
ready for traffic

LIFTING ASSEMBLY IN PLACE



Ready to lift timber bridge



One of twenty 50-ton hydraulic jacks

AVAILABLE CLEARANCES FOR POST-TENSIONING



Between bottom chord and siding




Between rail post and bottom chord

JACKING THE STRAND




Six ½" strands each side of each bottom chord, each pulled to 20,000 pounds

REMOVING TEMPORARY STRUCTURE




Removing temporary steel trusses



Reinstalling bridge rail

REPLACING THE DECK



Spiking done during night closures

PROJECT COMPLETE



Looking northwest, March 11, 2013

LIGHTING FOR SAFETY



INTERIOR NIGHT VIEW





Goodpasture Covered Bridge

HOLIDAY LIGHTING




Prior to rehabilitation local residents strung lights with extension cords



Programmable LED lighting installed

Circuitry concealed behind wrap-around siding



PICTURESQUE SETTING



Fall 2012
(prior to rehabilitation)



GOODPASTURE COVERED BRIDGE, 2013