



# CSI: Concrete Scene Investigation

What a Petrographer Can Determine About Your Concrete



[www.ASHGROVE.com](http://www.ASHGROVE.com)

The information contained in the presentation is solely for the intended recipient. Ash Grove makes no express or implied warranties of any kind in respect of the completeness of any information and/or opinions contained therein

**Bobby Bullard**  
**Geologist/Petrographer**

Ash Grove Cement – Technical Center  
Overland Park, Kansas



# What is Petrography?

- A branch of geology dealing with the description and classification of rocks (or in this case, concrete) mainly using microscopic examination of thin sections.

# Petrographic Analysis – How Can It Help?

- Identify Causes for Common Concrete Problems
  - Low Strength
  - Surface Deterioration
    - Scaling
    - Delamination
  - Cracking
    - Plastic Shrinkage
    - Alkali-Silica Reactivity
    - Sulfate Attack
    - D-Cracking
    - Reinforcement Corrosion

# Petrographic Analysis – How Can It Help?

- Customer Questions
  - Why?
  - How bad is it?
  - Can we live with it?
  - How can we prevent it next time?
- Petrographic Analysis
  - Determine cause(s) of inferior quality, distress, or deterioration
  - Determine extent of damage
  - Provide recommendations



# Concrete Scene Investigation #1

## Low Compressive Strength Cylinders

- The Usual Suspects:
  - Poor cylinder making
  - Poor cylinder testing
  - High air void content/void clustering
  - High water/cement ratio
  - Dirty aggregate
  - Early freezing



# Examination of the Cylinder

- Poor cylinder making
- Uneven loading



# Poor Testing Practices


- Misuse of pad caps
- Poor sulfur caps
- C 617 specification states
  - 1/4 in (6 mm) max average thickness
  - 5/16 in (8 mm) maximum thickness of any part of the cap






## Poor Field Curing (Early Age Freezing)

- Causes reduced strength and increased porosity
- Temperatures below 14°F, hydration and strength gain STOP



## Cylinder was made, cured, and tested correctly...



- Color
- Texture
- Paste/aggregate bond




# Polished Sections



Roughly  $\frac{3}{4}$ " thick  
4" X 4"



# Air Void System




## Air Void Parameters

- Total Air Content – 6%
- Specific Surface –  $>600 \text{ in}^2/\text{in}^3$
- Spacing Factor –  $<0.008 \text{ in.}$




# High Air Content

- For every 1% additional air, you lose 5% strength
- 10% air = 800 psi (in a 4000 psi mix with 6% design air)



# Air Void Clustering

- Causes poor paste/aggregate bond



# Thin Sections - What is a Thin Section?


- Piece of rock (or concrete, masonry, etc.) is glued to a glass slide
- Cut to 0.5 mm thickness
- Ground down to ~20 microns thickness





# Thin Sections

- Petrographic microscope (polarizing microscope or transmitted light microscope)



# Thin Sections


- Paste
  - Contents (residual cement, fly ash, slag, etc)
  - Distribution (uneven – retempering)
  - Hydration products (calcium hydroxide, etc)
- Aggregate – dirty

## Estimate of W/CM ratio

- Thin Section:
  - Amount and distribution of residual cement particles (and supplementary cementitious materials)
  - Comparison to standards
- In hand sample:
  - Color, Texture, and Luster of paste
  - Hardness of paste




# Residual Cement Particles





- Low w/c ratio ~0.40

- High w/c ratio ~ 0.60




# Overdose of Fly Ash

- Low strength
- Retarded set



# Dirty/Dusty Aggregate

Clean Aggregate




Dirty Aggregate

# Retempering

- All other things being equal, lighter colored paste = higher w/c ratio
- Inhomogeneous distribution of cement particles in paste

0.35 vs 0.55



# Perpetrator - Low Strength

- Evidence observed in as received sample, polished sections and thin sections
- Usually not just one suspect, can be a combination of several
- Example:
  - Addition of water at jobsite (retempering) lead to:
    - Air void clustering
    - Higher than designed air content
    - Higher than designed w/cm ratio
  - Then poor cylinder making resulted in:
    - Uneven cylinders
  - Poor testing practices led to:
    - Uneven sulfur capping – uneven loading
    - Erroneous compressive strength results?



# Concrete Scene Investigation #2 Surface Deterioration

- Scaling



# Scaling

- Usual Suspects:
  - High w/cm ratio ( $>0.45$ )
  - Poor air void system ( $<6\%$ , specific surface  $<600 \text{ in}^2/\text{in}^3$ , spacing factor  $>0.008 \text{ in}$ )
  - Improper finishing (before bleed water evaporates, overworking the surface)
  - Proper drainage ( $1/8 \text{ in/linear foot}$ )
  - Cement content  $<564 \text{ lbs/yd}^3$  (ASTM C 1084)
  - Less than 30 days of drying before exposure to deicing chemicals (AASHTO T260)

# Observations/Examination

- W/CM Ratio
  - Thin Section
- Air Void System
  - Polished Section
- Finishing
  - Both thin sections and polished sections




Image Source: PCA



# Finishing

- Finishing while bleed water is present/adding water “blessing”
  - Increases w/cm ratio at the surface
  - Increases porosity and likelihood of the ingress of moisture and salt solutions
  - Reduces abrasion resistance
- Over-finishing
  - Densifies surface and brings up excess paste
  - Decreases air voids at surface


# Carbonation

## Indication of porosity


- Phenolphthalein (indicator) changes to red at pH of ~8.6 to 10 (sound concrete ~12 to 13).
- $\text{Ca}(\text{OH})_2 + \text{CO}_2 = \text{CaCO}_3 + \text{H}_2\text{O}$
- Related to poor finishing, poor curing, and w/cm ratio



# Blessing/Working in Bleed Water




- Thin section at surface
- W/CM ratio ~ 0.57
- Higher porosity




- Thin section at depth
- W/CM ratio ~ 0.47


# Excessive Finishing



- Thin section at surface
- W/CM ratio  $\sim 0.40$




- Thin section at depth
- W/CM ratio  $\sim 0.55$



# Chemical Tests

- Cement Content (ASTM C1084)
  - Concrete sample is crushed, acid and base digested, residues measured. Calculations determine the amount of silica, and calcium which are related to the amount of cement in the mix.
- Chloride Content (AASHTO T260)
  - Concrete sample is crushed, acid digested, then chloride present is precipitated and detected using an electrode. This is related to the total amount of chloride ions in the sample.





# Perpetrator - Scaling

- Theory based on evidence from observation of field reports, polished sections, thin sections, and chemical data.
- Usually a combination of mix design, placing, finishing, curing, and treatment after placed.

# Concrete Scene Investigation #3 Durability Issues

- Alkali-silica reaction (ASR)
- D-Cracking

# ASR

- Map cracked surface
- White or clear gel
- Cracking through paste and aggregates





# ASR Detection: Staining Methods

- Uranyl Acetate
- ASR Detect™



# Potassium/Sodium Rich C-S-H Gel

## SEM/EDS Analysis



# D-Cracking

- Freeze/thaw damage to aggregates



**Figure 13.5:** Split and cracked carbonate rock particles after 5 cycles of freezing and thawing. Typical cracks along particle edges. (Magn. 0.35X; Photo by G. Woda)

# Polished section



# Conclusions

- Many variables affect concrete quality
- Petrographic analysis is a powerful tool but has limitations
  - Admixture types and dosage rates cannot be identified petrographically
  - Slump cannot be determined
- Additional information is helpful
  - Concrete age
  - Curing conditions
  - Mix design
- Good sample selection is important (i.e. taking cores from the problem area and a good area)





[www.ASHGROVE.com](http://www.ASHGROVE.com)