



Minnesota Timber Bridge Maintenance and Construction – A County Perspective

Brian Brashaw

University of Minnesota Duluth

Matthew Hemmila

St. Louis County, Minnesota

SmallWood 2010




April 21, 2010

UMD/St. Louis County, Minnesota Cooperation

- Training
- Inspections
 - Advanced inspection equipment
 - Hands-on and cooperative
- Research
 - Vibration monitoring approach
 - Load testing



USDA Forest Products Laboratory and University of Minnesota Duluth Publications








145

2004 8 2



St. Louis County Background


- Total Size
6,860 miles² (17,767 km²)
- Land
6,225 miles² (16,123 km²)
- Water
635 miles² (1,644 km²) 9.25%



Bridge Inventory

- 568 Bridges
- ~100 Timber Bridges
 - Timber girders or stringer
 - Panelized dowel laminated
 - Wheeler Consolidated bridges
 - Timber deck with steel girders


St. Louis County Index



Note: The reference material for this map was obtained through the cooperation of state, county and/or municipal government departments. A sincere effort has been made to produce an up-to-date map. However, with the various agencies we have to rely on, no guarantee can be made. All voluntary input for updating our road map will be accepted with gratitude.

Copyright, 1996-1999, County of St. Louis, Missouri. All rights reserved.

SLC BridgeMap 2004















Public Works Structure

Engineering

- Bridge Engineer
- 5 technicians
 - Inspections
 - Design for contractors & maintenance
 - Survey/topos

Maintenance

- Superintendent
- 2 four-man crews
 - Routine maintenance
 - Significant repairs
 - New construction

Bridge Program – Inspections

- Lots to do, not enough time
 - 170 every 12 months
 - Remainder on 24 month schedule
- Recent purchase and use of
 - Stress wave timers
 - Resistance microdrills






Bridge Program – Maintenance / Repairs



















Bridge Program Replacement

- Decision factors
 - Cost, site, span length, staffing
- Designs
 - Dowel laminated slab span
 - Panel-Lam from Wheeler
 - Copper naphthenate
 - Steel pilings



Recent Activity

- 2010 Superstructure replacement
Bridge 184
- 2009 Replacement Bridge 85.
- 2008 Superstructure replacement
Bridge 53; Nichols Lake
- 2007 Repairs to two bridges to
replace pile caps and partial
repairs to pilings

Bridge 53

- Steel girders with timber deck, timber pile caps and pilings
- 1964
- 22 ft span
- Restricted load ratings























Bridge 85

- 1946
- DF girders
- SYP pilings
- Timber deck
- Creosote
- 40 ft
- 2 spans
- 2 lanes





















Summary

- Timber will continue to be used on shorter spans
- Currently using Wheeler Panel-Lam systems installed by their own crews
- Steel pilings will be used for all replacements
- Ongoing emphasis on maintenance/repair
- Strategic research partnership with UMD is a priority

Acknowledgments

